

PRICE LIST VALIDATE FROM 1.1.2018

Service pricelist is for smaller orders (up to 100m)

For orders of a larger scale, we will gladly prepare for you a price offer with a significant discount**SEWAGE AND RESERVOIR LEAK TESTS**

Services	MU	MU excl. VAT	VAT	Price incl. VAT
SEWAGE LEAK TEST USING AIR PRESSURE TECHNOLOGY				
Pipeline DN 100 - 300mm	section	2 500,00	21%	3 025,00 CZK
Pipeline DN 301 - 400mm	section	2 900,00	21%	3 509,00 CZK
Pipeline DN 401 - 600mm	section	3 500,00	21%	4 235,00 CZK
Pipeline DN 601 - 800mm	section	3 900,00	21%	4 719,00 CZK
Pipeline DN 801 - 1000mm	section	4 900,00	21%	5 929,00 CZK
Pipeline DN 1001 - 1200mm	section	5 900,00	21%	7 139,00 CZK
Sealing of branches on tested section	pc	300,00	21%	363,00 CZK
Revision shaft leak test using compressed air	pc	4 000,00	21%	4 840,00 CZK
Repeat testing after unsuccessful results	hr	1 800,00	21%	2 178,00 CZK

RESERVOIR AND SEWAGE TANK LEAK TESTS ACCORDING TO ČSN 75 0905 STANDARDS

The price will be determined individually on the basis of personal examination.

FLAT FEE FOR VEHICLE DEPARTURE - PRAGUE, BEROUN, KLADNO, ROZTOKY

Vehicle: Renault Trafic, VW Transporter	dep	500,00	21%	605,00 CZK
---	-----	---------------	-----	-------------------

FLAT FEE FOR VEHICLE DEPARTURE - ŘÍČANY

Vozidlo: Renault Trafic, VW Transporter	dep	690,00	21%	834,90 CZK
---	-----	---------------	-----	-------------------

If the order is for outside these areas we do not charge the flat fee, but instead charge per kilometre from our base (K Hájům 7, Prague 5 - Stodůlky) to the customer and back.

Transport price per 1 km for orders outside the above-mentioned towns/city: Renault Trafic, VW Transporter: CZK 15/km

Price for air-pressure leak test includes:

- Fastening of 2 pressure valve pieces to the pipeline (and 1 pressure valve inlet cover piece for the revision shaft test)
- Carrying out the test to the required standards
- Evaluation of the test and issuing of the report

Compressed air test requirements: pipeline and the bottom of the revision shaft must be clean, in order for the equipment to access the revision shaft and fasten pressure valves to branches of the tested section.

Free water surface test requirements: the reservoir must be clean and filled with clean water (not included in the price of the pressure test) in order to fasten the pressure valve on the reservoir inlet.

We carry out leak tests according to ČSN EN 1610 and ČSN 75 0905 standards.

In the event of repeating previous unsuccessful tests, we will increase the price for time spent on repeated testing.

The final rate of VAT will be charged according to the valid Act No. 235/2004 Coll. and its amendments.